

ਵੱਲੋਂ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ : 1 ਲੇ:ਨਿ:ਵਿ:
ਭ ਤੇ ਮ ਸਾਖਾ ਮਲੇਰਕੋਟਲਾ।

ਵੱਲੋਂ


ਪ੍ਰਿਸ਼ੀਪਲ,
ਪਾਇਨੀਅਰ ਕਾਨਵੈਂਟ ਸਕੂਲ,
ਪਿੰਡ- ਗੱਜਣਮਾਜਰਾ, ਜਿਲ੍ਹਾ- ਮਲੇਰਕੋਟਲਾ।

ਨੰਬਰ 307 ਮਿਤੀ 15-09-2022

ਵਿਸ਼ਾ: ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਲੈਣ ਸਬੰਧੀ।
ਹਵਾਲਾ: ਆਪ ਜੀ ਦਾ ਪੱਤਰ ਨੰਬਰ-PCS/XXII/22, ਮਿਤੀ 15/09/2022 ਦੇ ਸਬੰਧ ਵਿੱਚ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਇਸ ਉਪ ਮੰਡਲ ਦੇ ਸਹਾਇਕ ਇੰਜੀਨੀਅਰ ਸ੍ਰੀ ਚਰਨ ਸਿੰਘ ਵੱਲੋਂ ਬਿਲਡਿੰਗ ਦਾ ਨਿਰੀਖਣ ਕਰਨ ਉਪਰੰਤ ਰਿਪੋਰਟ ਕੀਤੀ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਸਾਲ 2022-23(31-03-2023) ਤੱਕ ਬਾਹਰੇ ਦੇਖਣ ਵਿੱਚ ਸੇਫ ਜਾਪਦੀ ਹੈ। ਇਸ ਤੋਂ ਇਲਾਵਾ ਇਹ ਵੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਵਿੱਚੋਂ ਜੇਕਰ ਕੋਈ ਵੀ ਅਡੀਸੀਨਲ ਅਲਟਰੇਸਨ ਕਰਨੀ ਹੈ ਤਾਂ ਕਿਸੇ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਵਾਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ। ਜੇਕਰ ਹੜ, ਕੁਦਰਤੀ ਆਫਤ ਨਾਲ ਕੋਈ ਵੀ ਦੀਵਾਰ, ਨੀਹਾਂ ਬਹਿੰਦੀਆਂ ਹਨ ਤਾਂ ਉਸ ਬਾਰੇ ਵੀ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਵਾਉਣ ਉਪਰੰਤ ਤਸਦੀਕ ਵੀ ਕਰਵਾਇਆ ਜਾਵੇ। ਇਸ ਦੀ ਇੰਨਸਪੈਕਸਨ ਫੀਸ ਇਸ ਦਫਤਰ ਵੱਲੋਂ ਜੀ.ਆਰ ਨੰਬਰ 663544, ਮਿਤੀ 15-09-2022 ਰਾਹੀਂ 10,000/ ਜਮਾਂ ਕਰਵਾ ਲਈ ਹੈ।


ਨੱਥੀ/ਸਰਟੀਫਿਕੇਟ


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ : 1 ਲੇ:ਨਿ:ਵਿ:
ਭ ਤੇ ਮ ਸਾਖਾ ਮਲੇਰਕੋਟਲਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ-

ਮਿਤੀ-

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ, ਲੇ.ਨਿ.ਵਿ, ਭ ਤੇ ਮ ਸਾਖਾ, ਮਲੇਰਕੋਟਲਾ ਜੀ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ-4077, ਮਿਤੀ 15-09-2022 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾਂ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ : 1 ਲੇ:ਨਿ:ਵਿ:
ਭ ਤੇ ਮ ਸਾਖਾ ਮਲੇਰਕੋਟਲਾ।

Building safety report


Name of School:-Pioneer Convent School,

Gajjan Majra.(Distt. Malerkotla)

As per report of Sh. Charan Singh Assistant Engineer on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions:-

1. However, the Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
2. In case any addition, alteration, expansion and modification to this building are required to be done, regarding this inspection of undersigned may be arranged and obtained a certificate after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained be from the competent Authority.
6. The owner of the building/ Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report is for the covered area of the building as per Drawing submitted by the owner.
8. This report is not valid for legal purpose.

As per visually inspection as reported by the concerned Assistant Engineer the above building may be used for normal use for One year up to 31/03/2023 subject to the above conditions.


Sub-Divisional Engineer,
Const. Sub Division no 1,
PWD B&R Malerkotla.

